

**950N-3203 NEOBE LIGHTBAR**  
0115 - FACTORY SETTING FLASH PATTERN

**Mode 1**

+12 vdc **ORANGE** Control Wire Activated

Front & Corner Warning Lamps: *Corners Only- 6 pulse Neobe*

Rear & End Warning Lamps: *Off*

**Mode 2**

+12 vdc **ORANGE & BLUE** Control Wires Activated

Front & Corner Warning Lamps: *Inboard/Outboard with Corners - 6 pulse Neobe*

Rear & End Warning Lamps: *Inboard/Outboard without End - 6 pulse Neobe*

**Mode 3**

+12 vdc **ORANGE, BLUE & WHITE/BLACK** Control Wires Activated

Front & Corner Warning Lamps: *Inboard/Outboard with Corner - 6 pulse Neobe*

Rear & End Warning Lamps: *Inboard/Outboard without End - 6 pulse Neobe*

***Any other combinations of the ORG, BLUE and WHITE/BLACK control wires = OFF.***

***See 950N-3203 Appendix A for additional 950N-3203 Control & Power Wire functions.***

***Optional Feature that may be ordered:***

***Bonded Power Cable (Removes Control Cable) - Activates in Mode 3***